


FLUSH!

Following the replacement of a lead or galvanized service line, small pieces of lead or other debris can enter the pipes in your home. It is important you flush your plumbing thoroughly using these simple steps:


1. Remove aerators from all cold water taps.



2. Starting in the lowest level of your home, fully open all cold water taps in sinks, tubs and showers. Be sure drains are clear!



3. Wait 30 minutes.



During this time check that your drains are draining freely.

4. Starting at the top floor, turn off all faucets. (Clean and re-install aerators.)
5. All customers should run one cold water tap for 3-5 minutes daily before using water for drinking or cooking to remove lead that may leach from your pipe solder or faucets.